

IN THE SPECIFICATION

Please replace paragraph [0020] beginning at page 8, line 2, with the following rewritten paragraph:

[0020] In this case, the ~~rubricating~~ lubricating oil which has been introduced to the coupled portion of the splines 54 and 56 flows efficiently to the through hole 74 side through the axial direction oil passage 78, the axial direction oil passage 78 is formed in a portion that extends over to the far edge of the through hole 74, this portion including the portion corresponding to the through hole 74, and the spline tooth 76 remains extending from the far edge of the through hole 74. Therefore, the lubricating oil temporarily stops in the axial direction at the portion corresponding to the through hole 74, and flows outside the rotating drum through the through hole 74, and is supplied to the frictional plates 62 and 64 efficiently.